

# Oil Field Environmental Incident Summary

**Incident:** 20140317172333 **Date/Time of Notice:** 03/17/2014 17:23

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** Donald Peterson CTB

**Field Name:** SMITH

**Well File #:**

**Date Incident:** 3/17/2014 **Time Incident:** 08:30 **Facility ID Number:** 211777-01

**County:** RENVILLE **Twp:** 160 **Rng:** 86 **Sec:** 28 **Qtr:** NE NE

**Location Description:** Spill occurred onsite at the Donald Peterson CTB also referred to as the Smith Central Tank Battery

**Submitted By:** Brian Wurm

**Received By:**

**Contact Person:** Brian Wurm  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:** 0.3 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels	10	barrels
Brine	15	Barrels	15	Barrels	15	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:** **Written Report Received:** 11/27/2015 **Clean Up Concluded:** 4/1/2014

**Risk Evaluation:**

None noted

**Areal Extent:**

**Potential Environmental Impacts:**

None noted

**Action Taken or Planned:**

Production was switched to alternate treater on location to stop release. A vac truck will be brought in to pick up all free liquids and impacted material will be removed as necessary. Treater will be brought back into use once the firetube is replaced.

**Wastes Disposal Location:** Recovered oil will be returned to production tank on site, recovered water will be taken to disposal and impacted facility soil will be taken to appropriate disposal.

**Agencies Involved:****Updates**

---

**Date:** 5/12/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from a treater leak remained on location within the diking, according to the report. NDIC retains oversight.